

Service Codes for KIRK 50X0 Handset

03/08/2021 20:32:45

[FAQ Article Print](#)

Category:	Hardware Endgeräte::Telefone::Polycom::KIRK, KWS	Votes:	0
State:	public (all)	Result:	0.00 %
Language:	de	Last update:	03/09/2012 10:43:50

Keywords

KIRK Polycom 5020 5040 Factory Reset lpei code

Symptom (public)

Das Polycom KIRK 50X0 bietet verschiedene Codes, mit denen verschiedene Informationen angezeigt, sowie ein Factory-Reset durchgeführt werden können.

Problem (public)

Solution (public)

Möglicherweise funktionieren ein oder mehrere Codes nicht, da die Implementierung der Codes auf der Firmware und Softwareversion beruht

To enter a Service Code - enter the requested code and press OFF-HOOK key.

- *99950* - Delete phone book, speed dial list, message templates and all subscriptions
- *99951* - Delete Phonebook and speed dial list
- *99954* - Delete all subscriptions
- *99968* - Enable B-answer when placed in charger
- *99977* - Vibrator, buzzer and display test
- *99988* - Show handset up-time
- *99989* - Test display for measuring radio performance/coverage